

## **Appendix B**

---

### **Representative Site Photographs (electronic only)**

**GEI Consultants, Inc.**

**PHOTOGRAPHIC RECORD**

---

**Project:** Fulton Municipal Works Former MGP Site  
**Remedial Investigation**  
**Location:** Brooklyn, New York



**Photographer:** M. Felter  
**Date:** 4/23/10  
**Photo No.:** 1  
**Direction:** SE

**Comments:**  
Parcel 1 (270 Nevins Street) at the intersection with Degraw Street. Parcel I is to the right. Parcel III is located to the left.



**Photographer:** M. Felter  
**Date:** 6/6/08  
**Photo No.:** 2  
**Direction:** NE

**Comments:**  
Parcel 1 – Inside Warehouse

**GEI Consultants, Inc.**

**PHOTOGRAPHIC RECORD**

---

**Project: Fulton Municipal Works Former MGP Site  
Remedial Investigation  
Location: Brooklyn, New York**



**Photographer:** M. Felter  
**Date:** 6/26/08  
**Photo No.:** 3  
**Direction:** NW

**Comments:**  
Parcel II – Playground Area



**Photographer:** M. Felter  
**Date:** 1/16/08  
**Photo No.:** 4  
**Direction:** N

**Comments:**  
Parcel II – Pool Area



**GEI Consultants, Inc.**

**PHOTOGRAPHIC RECORD**

---

**Project: Fulton Municipal Works Former MGP Site  
Remedial Investigation  
Location: Brooklyn, New York**



**Photographer:** M. Felter  
**Date:** 1/16/08  
**Photo No.:** 5  
**Direction:** NE

**Comments:**  
Parcel II –Handball Court Area



**Photographer:** M. Felter  
**Date:** 1/16/08  
**Photo No.:** 6  
**Direction:** NE

**Comments:**  
Parcel II – Sidewalk Area with Tree  
Wells (Planters)

GEI Consultants, Inc.

PHOTOGRAPHIC RECORD

---

Project: Fulton Municipal Works Former MGP Site  
Remedial Investigation

Location: Brooklyn, New York



**Photographer:** M. Felter

**Date:** 1/16/08

**Photo No.:** 7

**Direction:** E

**Comments:**

Parcel III – Outside Adams Book Co.  
Warehouse



**Photographer:** J. Sandorf

**Date:** 3/14/10

**Photo No.:** 8

**Direction:** SW

**Comments:**

Parcel III – Inside Adams Book Co.  
Warehouse

**GEI Consultants, Inc.**

**PHOTOGRAPHIC RECORD**

---

**Project: Fulton Municipal Works Former MGP Site  
Remedial Investigation  
Location: Brooklyn, New York**



**Photographer:** M. McLeod  
**Date:** 11/10/09  
**Photo No.:** 9  
**Direction:** NE

**Comments:**  
Parcel IV – Outside Truck  
Maintenance and Roll-off Box Storage  
Area



**Photographer:** L. Willey  
**Date:** 3/26/10  
**Photo No.:** 10  
**Direction:** W

**Comments:**  
Parcel V – Outside Brooklyn Boulder



**GEI Consultants, Inc.**

**PHOTOGRAPHIC RECORD**

---

**Project:** Fulton Municipal Works Former MGP Site  
**Remedial Investigation**  
**Location:** Brooklyn, New York



**Photographer:** L. Willey  
**Date:** 3/26/10  
**Photo No.:** 11  
**Direction:** NE

**Comments:**  
Parcel V – Inside Brooklyn Boulders



**Photographer:** Jen Sandorf  
**Date:** 3/14/10  
**Photo No.:** 12  
**Direction:** SW

**Comments:**  
Parcel V – Inside Royal Items  
Warehouse

**GEI Consultants, Inc.**

**PHOTOGRAPHIC RECORD**

---

**Project: Fulton Municipal Works Former MGP Site  
Remedial Investigation  
Location: Brooklyn, New York**



**Photographer:** L. Willey  
**Date:** 11/10/09  
**Photo No.:** 13  
**Direction:** E

**Comments:**  
Parcel VI – Inside Brooklyn Truck &  
Equipment Repair/ Parking Area Next  
to Canal.